

# TALKEETNA AIRPORT

## **Contents:**

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2002
- A Branch PCI Condition Report
- A Section PCI Condition Report

## **Airport Information:**

- Location:  
The Talkeetna Airport is located approximately 1 mile east of the Talkeetna, Alaska in South Central Alaska. The airport is approximately 115 air miles north of Anchorage.
- District: Mat-Su, South Central
- Airport Manager: Steve Hanson
- District Maintenance Manager: Durt Devon
- Pavement Surface:  
There are over 690,000 square feet of asphalt concrete paved surfaces at the Talkeetna Airport.
- Last Pavement Construction: 1988
- Pavement layout:  
The airport consists of Runway 18-36, four Taxiways, and an Apron. Taxiways A, B, and D were constructed and paved in 1996. At that time, Taxiway A was made into a full-length parallel taxiway. The rest of the airport paving was constructed in 1988.
- Design Aircraft:
- 2001 Enplanements: 1,218
- Airport Class: Non-Primary
- Last pavement condition survey: 2001
- Next planned pavement condition survey: 2004
- 2002 reported pavement maintenance and/or changed conditions:  
No reported pavement maintenance.
- Recommendations: See PCI maps